





INDICATE NORTH - NAME ADJOINING ROADWAY AS BASE LINE

SEPTIC TANK LEVEL \_\_\_\_\_ CLEANOUTS \_\_\_\_\_

DISTRIBUTION BOX LEVEL \_\_\_\_\_

DRAIN FIELD/TITLE DEPTH \_\_\_\_\_ FT. TRENCH WIDTH \_\_\_\_\_ FT. INLET DEPTH \_\_\_\_\_ FT.

EFFECTIVE GRAVEL DEPTH \_\_\_\_\_ FT. TOTAL LENGTH \_\_\_\_\_ FT.

NUMBER OF TRENCHES \_\_\_\_\_ ONE SIDEWALL/BOTTOM AREA \_\_\_\_\_ SQ. FT.

DRYWALL INSIDE DIAMETER \_\_\_\_\_ FT. EFFECTIVE DEPTH BELOW INLET \_\_\_\_\_ FT.

ABSORBENT AREA \_\_\_\_\_ SQ. FT.

REMARKS: 12/19/93 - DRY WELL FULL BUT TRENCH NOT  
 CONNECTED TO DW THEREFORE NOT USED BUD  
 ARNOLD CONNECTED TRENCH TO DW. BUD ARNOLD  
 NOTED THAT TRENCH HAD LESS THAN 7 FT STONE  
 CAST IRON PIPE BETWEEN TANK & DRY WELL  
 TO BE REPLACED NO NEW TRENCH OLD TRENCH  
 TO BE USED

DATE SYSTEM APPROVED 12/19/93 INSPECTOR R. Hodges