



Howard County  
Health Department

**BUREAU OF ENVIRONMENTAL  
HEALTH**

7178 Columbia Gateway Drive,  
Columbia, MD 21046

Phone (410) 313-2640 Fax (410) 313-2648

TDD (410) 313-2323

Toll Free 1-866-313-6300

Website: [www.hchealth.org](http://www.hchealth.org)

**FAX**

To: Attention: Brian Benchmark Engineering, Inc.	From: Dana Bernard
Fax: (410) 465-6644	Pages: 2
Phone: (410) 465-6105	Date: 11/17/2008
Re: Carroll Mill Road ( Lot # 1)	cc:

Comments:

If you have any questions or correspondence, I can be reached at the above address or by telephone at (410) 313-2775.

Thanks,

*Dana L. Bernard*


Dana L. Bernard, Sanitarian  
Bureau of Environmental Health  
Well and Septic Program

Phone (410) 313-2775

Fax (410) 313-2648

E-mail: [DBernard@howardcountymd.gov](mailto:DBernard@howardcountymd.gov)

**IMPORTANT WARNING:** This message is intended for the use of the person or entity to which it is addressed and may contain information that is privileged and confidential, the disclosure of which is governed by applicable law. If the reader of this message is not the intended recipient, or the employee or agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this information is **STRICTLY PROHIBITED**. If you have received this message in error, please notify the sender immediately and arrange for the return or destruction of these documents.



Bureau of Environmental Health  
7178 Columbia Gateway Drive, Columbia, MD 21046-2147  
(410) 313-2640 Fax (410) 313-2648  
TDD (410) 313-2323 Toll Free 1-866-313-6300  
website: www.hchealth.org

---

Peter L. Beilenson, M.D., M.P.H., Health Officer

November 17, 2008

RE: **Percolation Test Results**

Purpose: Create a New Lot and Establish Septic Reserved Area

Property ID: Carroll Mill Road (Pride's Crossing Lot #1)

Ellicott City, Maryland 21742

Tax Map: 23, Parcel: 79


Dear Mr. and Mrs. Brasher:

Percolation testing was recently conducted October 21, 2008 on the above referenced property, in an effort to establish sufficient septic reserve area and create a new lot.

Results indicate satisfactory soil conditions for onsite wastewater disposal and adequate septic reserve area to support the proposed number of bedrooms for a single family dwelling.

A total of 6 test holes were dug. Field data collected is shown on the Percolation Test Worksheets enclosed with this letter. A new reserve area with 2 repairs was established on the lot. Acceptable ranges for recommended inlet and trench bottom depth, and usable sidewall are indicated, and may be confirmed at the time of installation.

The next step in this process is to have your engineer / consultant submit a Percolation Certification Plan. If you have any questions regarding this evaluation or requirements for the Percolation Certification Plan, please contact me at the above address or by telephone at (410) 313-2775.

Respectfully,  
  
Dana L. Bernard, Sanitarian  
Bureau of Environmental Health  
Well and Septic Program  
Phone (410) 313-2775  
Fax (410) 313-2648  
E-mail: DBernard@howardcountymd.gov

DLB

Enclosure

cc: Well & Septic program file  
Benchmark Engineering, Inc.