



HOWARD COUNTY HEALTH DEPARTMENT

Diane L. Matuszak, M.D., M.P.H., County Health Officer
December 27, 1999

Ms. Mary Smoot
17221 Hardy Road
Mt. Airy, MD 21771

RE: Replacement Well Sampling
17221 Hardy Road
Well Permit # HO-94-2443


Dear Mr. Cremeans:

This office is requesting that you contact the Community Environmental Health Services Program at (410) 313-2644 to schedule an initial water sampling for the referenced replacement well, as required by the Maryland Well Construction Regulation (COMAR 26.04.04).


It is preferred that the sample be collected from an indoor tap, but if suitable scheduling is not completed, the sample may be taken from an outside tap to complete your sampling obligation. However, the potential for unsuccessful sample results increases when samples are collected from taps exposed to the outside environment.

Failure to confirm the potability of this well water supply by completion of water sampling requirements could result in the issuance of an order to abandon and seal the well in accordance with COMAR 26.04.04.

If you have any questions, please call me at (410)313-2640. Thank you for your attention to these important matters.

Approving Authority

Registered Sanitarian
Water and Sewerage Program

MR
cc: File



Bureau of Environmental Health

8930 Stanford Blvd, Columbia, MD 21045
Main: 410-313-2640 | Fax: 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300
www.hchealth.org

Maura J. Rossman, M.D., Health Officer

MEMORANDUM

TO: Homeowner
17221 Hardy Road
Mt. Airy, MD 21771

FROM: Sarah Collins, L.E.H.S. SEC
Howard County Health Department
Well and Septic Program

DATE: December 30, 2016

RE: Old well at 17221 Hardy road

During a repair to the septic system in December of 2016, the Health Department observed an old pit well in close proximity to a drilled well with tag # HO-94-2443.

The pit well must be sealed by a licensed well driller and documentation should be submitted to the Health Department that this task has been completed. A well not in use can lead to contamination of groundwater and is a potential health threat to people drinking water in the area.

Please contact me at 410-313-6287 or SCollins@howardcountymd.gov with any questions.

Cc: File

Collins, Sarah

From: Courtney Odum-Duncan <courtney@odumrealestate.com>
Sent: Friday, January 13, 2017 10:03 AM
To: Collins, Sarah
Subject: Well at 17221 Hardy Road
Attachments: HCHD well report.pdf

Hi Ms. Collins, I am writing regarding your letter (attached) about the well at 17221 Hardy Road. I am the agent representing the buyers who just purchased the house.

The well pit is still in use. Here is an excerpt from the recent well inspection:

The new well drilled in 2008 is attached to the old well, located in the well pit in the back yard. The pressure tank was functional and the neutralizer located in the basement is being serviced in 2016.

I hope that satisfies the county's concern. Please let me know if there is anything else we need to do.

Courtney Odum-Duncan, Realtor
RE/MAX 100
443-838-3782
www.odumrealestate.com



courtney@mrjs.com is no longer in use. Please change my email to courtney@odumrealestate.com in your address book. Thank you!

1/13/17

Spoke with John Moseman at Well Water Solutions. Pit in the backyard does not have a well - only contains pumping equipment for new well. (sc)