

12
10:00

APPLICATION

PERCOLATION TESTING

A _____
P 48169

HOWARD COUNTY HEALTH DEPARTMENT
BUREAU OF ENVIRONMENTAL HEALTH
P.O. BOX 476 ELLICOTT CITY, MARYLAND 21043
TELEPHONE 461-9933

*PREVIOUS OK -
REPAIR PERC TO
ESTABLISH CAPACITY
TO SUPPORT PROPOSED
ADDITIONAL C.W.*

DISTRICT _____
DATE 5/28/92

TO: THE COUNTY HEALTH OFFICER
ELLICOTT CITY, MARYLAND

I, HEREBY, APPLY FOR THE NECESSARY TEST IN ORDER TO CONSTRUCT (OR RECONSTRUCT) A SEWAGE DISPOSAL SYSTEM.

PROPERTY OWNER SHANNON HOPKINS

ADDRESS 18805 PENNSHOP RD MEADLEY 21771 PHONE _____

PROSPECTIVE BUYER _____

ADDRESS _____ PHONE _____

PROPERTY LOCATION:

SUBDIVISION _____ LOT NO _____

ROAD AND DESCRIPTION _____

TAX MAP 6 PARCEL # 12 (0.31 Acres) Built 1950 Ex Bldg Size 780 sqft

SIZE OF LOT _____ TYPE BLDG _____
(SINGLE FAMILY DWELLING OR COMMERCIAL)

THE SYSTEM INSTALLED UNDER THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBLIC FACILITIES BECOME AVAILABLE. I FULLY UNDERSTAND THE FEE CONNECTED WITH THE FILING OF THIS PERC TEST APPLICATION IS NON-REFUNDABLE UNDER ANY CIRCUMSTANCES. I ALSO AGREE TO COMPLY WITH ALL M.O.S.H.A. REQUIREMENTS IN TESTING THIS LOT.

(SIGNATURE OF APPLICANT)

APPROVED BY _____ FOR _____ DATE _____

REJECTED BY _____ FOR _____ DATE _____

HOLD PENDING FURTHER TESTS _____ DATE _____

REASONS FOR REJECTION OR HOLDING _____

HD-216

THIS IS NOT A PERMIT

June 9, 1992

Mr. Craig Williams, Program Director
Howard County Health Department
3525-H Ellicott Mills Drive
Ellicott City, Maryland 21043-4544

RE: Permit for Relocation of Septic System
to property at 18805 Penn Shop Road

Dear Mr. Williams,


As a result of the positive percolation repair test inspection conducted on June 2, 1992, we are submitting the following proposal for your review and consideration:

EXISTING SEPTIC SYSTEM:

Drain and/or fill tank with rock and soil. (1000 GAL TANK TO BE REPLACED AT LOCATION TO BE DETERMINED AT TIME

EXISTING WELL:

Revision of site plan drawings have been made (attached) so as to not impact existing well. (OF INSTALLATION INSPECTION, AND CONNECTED TO EXISTING DRAIN FIELD)




Thank you for your prompt coorespondence and verification of positive re-inspection. We look forward to hearing from you again soon.

Sincerely,



Robert R. Hopkins



Shannon L. Hopkins

Property Owners of
18805 Penn Shop Road
Mt. Airy, MD 21771

92 JUN 16 11 17:20

OK AS PROPOSED

BP APPLICATION PENDING

6/16/92 Craig Williams - How. Co. Health.





HOWARD COUNTY HEALTH DEPARTMENT

Joyce M. Boyd, M.D., County Health Officer

June 3, 1992

Reply to:

Mr. Robert Hopkins
18805 Penn Shop Road
Mt. Airy, Maryland 21771

RE: Percolation Repair Test Inspection
18805 Penn Shop Road

Dear Mr. Hopkins:

On May 18, 1992, a percolation repair test inspection was conducted at the above referenced property. This was requested to evaluate the property's capacity to handle the potential increase in sewage flow in advance of your submittal of a building permit application for an addition to the existing residence.

The preliminary decision rendered by the inspecting sanitarian was that soil conditions were not satisfactory because the rock content below 6 feet was judged to be excessive and percolation rates at shallow depths were unreasonably slow. Per your request, a reinspection was conducted on June 2, 1992. The results of the re-examination were favorable. Soil conditions, while less than ideal, were judged acceptable for septic repair.

Limited lot area with the existing structure, well and septic system in close proximity to one another is the principle restrictive feature in determining the acceptability of a proposed addition. Further review is contingent upon receipt of a scaled site plan of your proposed addition which adequately addresses concerns about potential conflicts with the location of the existing well and septic system.

The proposal originally presented would have required replacement of the existing well, which would have been very difficult, given the location of septic systems on this and surrounding properties. A proposal which does not impact the existing well and which impacts the existing septic system as little as possible, would seem more appropriate to this property.

Bureau of Environmental Health
3525-H Ellicott Mills Drive Ellicott City, Maryland 21043-4544
Water and Sewerage, Permits 461-9933 Community Environmental Health 461-9944
Technical Services 461-9955 Director 461-9956 TDD 313-2323




Mr. Robert Hopkins

(2)

June 3, 1992

If you have any questions regarding this matter or wish to present a specific site plan for consideration, please call this office (313-2640) to discuss this matter.

Very truly yours,



Craig Williams, Program Director
Water and Sewerage Program

CW:jr

cc: Mr. Ronald Pinkley, R. S.
File

