



Total linear feet of trench required 300 feet

Width of trench(es) 3.0 feet

Depth of trench(es) 4.0 feet

Depth of stone required below distribution pipe 2.0 feet

Approved Septic System Plan
Howard County Health Department

Note: Shown adjustment to septic tank & elevations are per FAX from Abey, Eckert

Amey W. Mc...
Signature _____ Date 1/25/01

CLARK • FINEFROCK & SACKETT, INC.
ENGINEERS • PLANNERS • SURVEYORS

7135 MINSTREL WAY • COLUMBIA, MD 21045 • (410) 381-7500 BALT. • (301) 621-8100 WASH.

res not sewer by gravitu