



APPLICATION

FOR PERCOLATION TESTING AND SITE EVALUATION

TEST DATE(S) _____ TEST TIME _____ NO 535973

AGENCY REVIEW: _____ DATE 09/12/11

DO NOT WRITE ABOVE THIS LINE

I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S) TO:

CHECK AS NEEDED:

- CONSTRUCT NEW SEPTIC SYSTEM(S)
- REPAIR/ADD TO AN EXISTING SEPTIC SYSTEM
- REPLACE AN EXISTING SEPTIC SYSTEM

CHECK AS NEEDED:

- NEW STRUCTURE(S)
- ADDITION TO AN EXISTING STRUCTURE
- REPLACE AN EXISTING STRUCTURE

CHECK ONE:

- CREATE NEW LOT(S)
- BUILD ON AN EXISTING LOT IN A SUBDIVISION
- BUILD ON AN EXISTING PARCEL OF RECORD

IS THE PROPERTY WITHIN 2500' OF ANY RESERVOIR?

- YES
- NO

THE TYPE OF STRUCTURE IS:

- RESIDENTIAL WITH 4 PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE (NOTE *UNKNOWN* IF APPROPRIATE)
- COMMERCIAL (PROVIDE DETAIL OF NUMBERS AND TYPES OF EMPLOYEES/ CUSTOMERS ON ACCOMPANYING PLAN)
- INSTITUTIONAL/GOVERNMENT (PROVIDE DETAIL OF NUMBERS AND TYPES OF EMPLOYEES/USERS ON ACCOMPANYING PLAN)

PROPERTY OWNER(S) Tiny Liang

DAYTIME PHONE 301-854-2902 CELL 202 489 4881 FAX _____

MAILING ADDRESS 12598 Clarksville Pike Clarksville MD.
STREET CITY/TOWN STATE ZIP

APPLICANT Ronnie Heaps

DAYTIME PHONE _____ CELL 443-277-7522 FAX 410 552 5825

MAILING ADDRESS 425 O Brecht Rd Sykesville MD 21784
STREET CITY/TOWN STATE ZIP

APPLICANT'S ROLE: DEVELOPER BUILDER BUYER RELATIVE/FRIEND REALTOR CONSULTANT

PROPERTY LOCATION
SUBDIVISION/PROPERTY NAME 12598 Clarksville Pike Rt108 LOT NO. _____

PROPERTY ADDRESS 12598 Clarksville Pike Rt108 Clarksville MD,
STREET TOWN/POST OFFICE

TAX MAP PAGE(S) _____ GRID _____ PARCEL(S) _____ PROPOSED LOT SIZE _____

AS APPLICANT, I UNDERSTAND THE FOLLOWING: THE SYSTEM INSTALLED SUBSEQUENT TO THIS APPLICATION IS ACCEPTABLE ONLY UNTIL PUBLIC SEWERAGE IS AVAILABLE. THIS APPLICATION IS COMPLETE WHEN ALL APPLICABLE FEES AND A SUITABLE SITE PLAN HAVE BEEN RECEIVED. I ACCEPT THE RESPONSIBILITY FOR COMPLIANCE WITH ALL M.O.S.H.A. AND "MISS UTILITY" REQUIREMENTS. APPROVAL IS BASED UPON SATISFACTORY REVIEW OF A PERC CERTIFICATION PLAN.

TEST RESULTS WILL BE MAILED TO APPLICANT. Ronnie Heaps
SIGNATURE OF APPLICANT

HOWARD COUNTY HEALTH DEPARTMENT, BUREAU OF ENVIRONMENTAL HEALTH, WELL AND SEPTIC PROGRAM
1718 COLUMBIA GATEWAY DRIVE COLUMBIA, MARYLAND 21046 (410) 313-2640 FAX (410) 313-2648
TDD (410) 313-2323 TOLL FREE 1-877-4MD-DHMH

A/P _____

Empty rectangular box for notes or data.

Empty rectangular box for notes or data.

Empty rectangular box for notes or data.

Large empty rectangular box for detailed notes or diagrams.

Empty rectangular box for notes or data.

Empty rectangular box for notes or data.

Empty rectangular box for notes or data.

DATE	TEST #	DEPTH	START	BREAK 1" DROP	STOP 2" DROP	TIME OF 2ND INCH	P/F/H

REMARKS _____

SANITARIAN _____ BACKHOE _____ OTHERS _____

TEST HOLES USED IN SDA _____ AVG. PERC TIME _____ SQ. FT/BR _____

TRENCH WIDTH _____ INLET DEPTH _____ MAX. BOT DEPTH _____ EFFECTIVE SW _____

12598 Clarksville Pk.

October 21, 2011

Mr. Jeff Williams,

Thank you for your consideration.

This confirms my request for a refund of the \$330 for Permits of Howard County inspection. Ronnie Heaps gave us bad information after he looked at the septic tank. He told us the pipe was fine but the old drain field failed and a new drain field needed to be constructed. Ronnie Heaps asked for a check from me payable to Howard County so that he could schedule a perc test and begin work as soon as possible. I gave the check of \$330 to Ronnie immediately after he "checked the pipe". He told me the check is the permit fees so Howard County would send someone to the site to assess and authorize a plan for replacement of the drain field.

Actually, the problem was a blockage of the pipe between the septic tank and the drain field. It was not the drain fiend failed. (However, Ronnie Heaps crushed and broke the pipe with his backhoe when he was checking the septic tank.) Therefore, no drain field repair or replacement work needed to be done.

We successfully employed an alternative remediation to avoid Ronnie's interest in making money by replacing the drain field. Finally, the septic system was made operational without the need for any repair or replacement work. Therefore, no perc testing or septic repair was performed. That is the reason I request the refund of \$330 fee back to me.

Thank you again.

Tiru Liang

10/24/11 - ok to issue refund. JW

October 27, 2011

(Mail Refund To – Tiru Liang)

- Sent to Fiscal Department on 10/27/2011

Thanks in advance

Curtis Hughes
Bureau of Environmental Health

cc: File