



HOWARD COUNTY HEALTH DEPARTMENT

74005

DATE 3/1/23

Received From

Foyles Septic Clean

PHONE #

410-795-5070

For

Panel Repair - 16206
Friedouck Rd.

- CASH
- CHECK

NO.

1825

Three hundred thirty

Dollars

\$330.00

Received By

Akin



Bureau of Environmental Health
 8930 Stanford Blvd | Columbia, MD 21045
 410.313.2640 - Voice/Relay
 410.313.2648 - Fax
 1.866.313.6300 - Toll Free

Maura J. Rossman, M.D., Health Officer

INFORMATION FORM - SEPTIC SYSTEM REPAIR/UPGRADE

Reason for Request:

- Failing System
- System relocation for proposed addition
- System upgrade for proposed addition
- Inadequate treatment zone
- Collapsed septic tank
- Collapsed drywell

Has the septic tank been pumped within the last month?

Yes Date pumped: _____
 No DW Full

Was a visual inspection of the septic tank and/or drain fields conducted?

Yes Explain observation: _____
 No _____

Existing system design

- Drywell
- Trench
- Mound
- Unknown
- Other: _____

Was a visual inspection of the sewage line conducted?

Yes
 No

Blockage Leading to the field

Yes Explain _____
 No _____

Is discharge surfacing on the ground?

Yes
 No

Additional Comments:

*For REPAIRS, are the owners proposing, or do they plan to add in the future any additions or modifications to the property, i.e. pools, living space additions, garages, etc? This information must be disclosed at the time of this application. The Health Department will not be able to accommodate requests in the field for property modifications unrelated to the repair request. Such requests may require an additional fee, testing, and submittal of a Percolation Certification Plan, if the property does not meet current Code and Regulations.

Septic Contractor: Fogle's Septic Clean Contractor's Phone: 410.745.5670
 Contractor's Address: 580 Obrecht Rd Sykesville 21784
 Property Address: 16221 Frederick Rd County File: 317319
 Subdivision: N/A Lot: N/A Year Built: 1965
 Owner's Name: Dylan Steele Existing bedrooms: 3
 Name of previous owners: Clark Existing bedrooms: _____
 Proposed bedrooms: _____

*A Sanitarian will be in contact within three business days, depending upon the urgency of the situation, to coordinate the scheduling/review of the repair or upgrade.

Prior to scheduling inspections, scaled plans should be submitted to clarify the nature of the addition.


Print out a copy of Real Property Data via Dept. of Taxation website _____ Indexed file found _____

If soil/site conditions are limited and sewer and/or Metro District status is not conducive to connection, the Sanitarian may recommend pursuit of Emergency Sewer Extension or Emergency Metro District Inclusion. The Owner should contact the Bureau of Utilities for details.

No permit is to be issued nor inspection to be scheduled without prior fee collection at the office unless an emergency exists.

The contractor is to notify the office of the emergency as soon as possible.

2/2020



Bureau of Environmental Health

8930 Stanford Boulevard, Columbia, MD 21045

Phone 410-313-2600 Fax 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300

www.hchealth.org

Facebook www.facebook.com/hchohealth

Twitter: @HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

APPLICATION

FOR PERCOLATION TESTING AND SITE EVALUATION

PROPERTY LOCATION

SUBDIVISION/PROPERTY NAME

PROPERTY ADDRESS 116231 Frederick Rd Woodbine 21797

TAX ACCOUNT # 317319 TAX MAP 07 GRID 11 PARCEL 289 LOT NO. N/A PROPOSED LOT SIZE (ACRES) 1.108

ZONING CATEGORY _____ TIER _____

PROPERTY OWNER(S) Dylan Steele

DAYTIME PHONE 301-514-4370 CELL _____ EMAIL dylan@steele-electrical.com

MAILING ADDRESS 116231 Frederick Rd Woodbine 21797

APPLICANT Fogles Septic Clean RELATIONSHIP TO OWNER: Contractor

DAYTIME PHONE 410-795-5670 CELL _____ EMAIL Kim@foglesiac.com

MAILING ADDRESS 580 Obrecht Rd Spkensville 21787

I HEREBY APPLY FOR THE NECESSARY TESTING/EVALUATION PRIOR TO ISSUANCE OF SEWAGE DISPOSAL SYSTEM PERMIT(S):

PROPERTY:

- SUBDIVISION: NUMBER OF LOTS INCLUDING RESIDUE _____
- SUBDIVISION CLASSIFICATION (PER DEPT. OF PLANNING AND ZONING) MAJOR MINOR
- CONSTRUCT NEW OSDS ON UNDEVELOPED LOT
- REPAIR OR REPLACE FAILING OSDS
- UPGRADE EXISTING OSDS

BUILDING:

- RESIDENTIAL WITH 3 EXISTING OR PROPOSED BEDROOMS IN THE COMPLETED STRUCTURE
- COMMERCIAL (PROVIDE DETAIL OF TYPE OF USE AND NUMBERS OF EMPLOYEES/CUSTOMERS ON ACCOMPANYING PLAN)

IS THE PROPERTY WITHIN 2500 FEET OF ANY RESERVOIR?

- YES
- NO

AS APPLICANT, I UNDERSTAND THE FOLLOWING:

- THIS APPLICATION IS VALID FOR TWO (2) YEARS FROM DATE OF FEE PAYMENT AND APPROVAL IS BASED UPON HEALTH OFFICER SIGNATURE OF A PERC CERTIFICATION PLAN PRIOR TO EXPIRATION OF THIS PERMIT.
- THE APPLICATION FEE IS NON-REFUNDABLE.
- THIS APPLICATION MUST BE ACCOMPANIED BY ALL APPLICABLE FEES AND A SUITABLE SITE PLAN IN ORDER TO BE PROCESSED.
- THIS IS A PUBLIC DOCUMENT.

I declare and affirm that to the best of my knowledge, the information contained herein is correct. I declare that I am the owner of the property or duly authorized to make this application on behalf of the owner. I agree to comply with all applicable state and county regulations.

By signature of this application, I hereby grant Howard County Health Department officials the right to enter onto the property for the purpose of inspecting the property as directly related to the requested permit/service.

[Signature] 2/29/15

SIGNATURE OF APPLICANT DATE

RECEIPT

Howard County, MD
HOWARD COUNTY HEALTH DEPARTMENT
ASCEND ONE BUILDING
Columbia, MD 21045
8930 STANFORD BLVD

Application: WS-SP-APP-23-00043
Application Type: EnvHealth/Well and Septic/Sewage Disposal System/Application
Address: 16221 Frederick RD,

Receipt No.	5939					
Payment Method	Ref Number	Amount Paid	Payment Date	Cashier ID	Received	Comments
Check	78528	\$165.00	03/01/2023	JUKING		Receipt # 74005
Work Description:	Repair / Perc 16221 Frederick rd					

RECEIPT

Howard County, MD
HOWARD COUNTY HEALTH DEPARTMENT
ASCEND ONE BUILDING
Columbia, MD 21045
8930 STANFORD BLVD

Application: WS-PT-23-00507
Application Type: EnvHealth/Well and Septic/Percolation Test/Application
Address: 16221 Frederick RD,

Receipt No.	Ref Number	Amount Paid	Payment Date	Cashier ID	Received	Comments
5938	78528	\$165.00	03/01/2023	JUKING		Receipt # 74005

Work Description:

Wolf, Kevin

From: Wolf, Kevin
Sent: Wednesday, June 21, 2023 8:53 AM
To: Jeff Palmer (jeff@foglesinc.com)
Cc: 'john@foglesinc.com'
Subject: 16221 Frederick Road | Design
Attachments: [Untitled].pdf

Jeff,
This design is not correct. Firstly, the existing septic tank is not in the location per the installation in the field. The proposed pump tank should also be placed in a location away from the existing swale as much as possible. I believe Jamie marked a location in the field at the time we were there for our layout inspection. Second, the trenches are not shown in the approved location. They should be placed around the passing perc test, closest to the existing gravel drive to the far back right property line (trenches were flagged, painted and staked). See below for approximate location:






In addition to the above, please provide pump detail information on the design plan along with a supplemental sheet with the pump spec's, make and model, and indicate the force main diameter. I can always meet back out there if you need, just let me know.

Thanks,

Kevin M. Wolf, LEHS, REHS/RS
Groundwater Mgmt. Sec. Supervisor
Well & Septic Program
Howard County Health Department
8930 Stanford Blvd.
Columbia, MD 21045
410-313-2645 (Office)
410-313-2648 (Fax)
www.hchealth.org
kwolf@howardcountymd.gov



 twitter.com/HoCoHealth
 facebook.com/HoCoHealth
 instagram.com/hocohealth

CONFIDENTIALITY NOTICE

This message and the accompanying documents are intended only for the use of the individual or entity to which they are addressed and may contain information that is privileged, confidential, or exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, you are hereby notified that you are strictly prohibited from reading, disseminating, distributing, or copying this communication. If you have received this email in error, please notify the sender immediately and destroy the original transmission.

