

# PERMIT

SEWAGE DISPOSAL SYSTEM

DEPARTMENT OF HEALTH AND MENTAL HYGIENE

P 513218  
A 50548-D  
REPAIR

DISTRICT \_\_\_\_\_

HOWARD COUNTY HEALTH DEPARTMENT  
BUREAU OF ENVIRONMENTAL HEALTH  
~~XXXXXX~~ 410-313-2640

INDEXED

DATE 1-10-2000  
evaluated  
DATE SYSTEM APPROVED 1/14/00  
INSPECTOR SRK/CW

Brian Sandberg (PAUL DIAMOND) IS PERMITTED TO INSTALL \_\_\_\_\_ ALTER X

ADDRESS 6279 Rockburn Hill Road, Elkridge, MD 21075 PHONE 410-379-8014

SUBDIVISION \_\_\_\_\_ LOT \_\_\_\_\_ ROAD 6279 Rockburn Hill Road

PROPERTY OWNER Brian Sandberg

ADDRESS 6279 Rockburn Hill Road, Elkridge, MD 21075

SEPTIC TANK CAPACITY \_\_\_\_\_ GALLONS

**BUILDING PERMIT SIGNED  
AND RETURNED**

NUMBER OF BEDROOMS 3

2-6-03 BOB 140251-DRECK + BOBm ELKRD OR

\_\_\_\_\_ SQUARE FEET PER BEDROOM

LINEAR FEET OF TRENCH REQUIRED \_\_\_\_\_

REPAIR - PURPOSE - To establish adequate septic repair area in support of proposed garage addition. Call for inspection when ground is opened so sanitarian can recommend repair. 1-10-2000

B00121661 - RECOMMENDED FOR APPROVAL, PROPOSED GARAGE

LOCATION IS NOT IN AREA POTENTIALLY USEFUL FOR FUTURE SEPTIC REPAIR.

NO FURTHER ACTION REQUESTED AT THIS TIME.

PLANS APPROVED BY Steven R. King / CW DATE 1/14/00

COVER NO WORK UNTIL INSPECTED AND APPROVED

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM

NOTE: CLEANOUT REQUIRED EVERY 70 FEET OF SEWER LINE AND/OR AT 90° SWEEPS IN LINES FROM HOUSE TO DRAIN FIELDS. 90° ELBOWS NOT ACCEPTABLE.

NOTE: ALL PARTS OF SEPTIC SYSTEMS (I.E. TANK, DISTRIBUTION BOX TRENCHES) TO BE 100 FEET FROM WELL (UNLESS OTHERWISE SPECIFICALLY AUTHORIZED)

NOTE: IF DEEP TRENCH(ES) ARE USED CALL FOR INSPECTION BEFORE AND AFTER PLACING GRAVEL IN TRENCH(ES)

NOTE: NO DRY WELL SHALL EXCEED 15 FOOT IN DIAMETER NO ABSORPTION TRENCH TO EXCEED 100 FEET IN LENGTH

NOTE: ALL PIPE FROM HOUSE TO SEPTIC TANK MUST BE CAST IRON OR SCHEDULE 35/40 PVC OR ABS

PERMIT VOID AFTER TWO YEARS


NOTE: INSTALL STAND PIPE ON SEPTIC TANK AND DRY WELL STAND PIPES MUST BE 6 INCHES IN DIAMETER CAST IRON, CONCRETE OR TERRA COTTA OR PVA OR ABS ACCEPTED. IF TOP OF SEPTIC TANK IS DEEPER THAN 3 FEET, MANHOLE TO GRADE REQUIRED.

NOTE: DISTRIBUTION BOXES MUST HAVE BAFFLES

**\*INSTALLER IS RESPONSIBLE FOR OBTAINING FINAL APPROVAL ON THIS PERMIT**

A 50548-D

Mole C



0'	Top Soil
4'	clay loam orange- w/ dark brown streaks
5'	silty clay loam orange- dark brown pockets of Silty loam
7.5'	75-85% rock fragments Solid Rock

uncertain depth of fill material

STEEP BEYOND THIS LINE

16'

50'

39'

17'

6"



outlet pipe 24" below grade destination unknown

EXISTING GARAGE

OLD CISTERN?

CONDITION OF EXISTING SYSTEM IS UNKNOWN

original hand dug well not in use but not sealed



SEPTIC TANK LEVEL N/A CLEANOUTS 6" on Septic Tank installed on 12/16/98 by Duarite/Septic Service per Dunrite

DISTRIBUTION BOX LEVEL N/A

DRAIN FIELD/TITLE DEPTH N/A FT. TRENCH WIDTH N/A FT. INLET DEPTH N/A FT.

EFFECTIVE GRAVEL DEPTH N/A FT. TOTAL LENGTH N/A FT.

NUMBER OF TRENCHES N/A ONE SIDEWALL/BOTTOM AREA N/A SQ. FT.

DRYWALL INSIDE DIAMETER N/A FT. EFFECTIVE DEPTH BELOW INLET N/A FT.

ABSORBENT AREA N/A SQ. FT.

REMARKS: 1/14/00 - PERC HOLE DUG IN LOCATION A & B (SEE PROFILE) HOLE A DUG IN THE AREA MOST POTENTIALLY SUITABLE FOR FUTURE SEPTIC SYSTEM REPAIR, HOLE A UNSUITABLE FOR FUTURE SYSTEM INSTALLATION. HOLE B DUG IN AREA OF PROPOSED GARAGE ADDITION. HOLE B NOT SUITABLE FOR FUTURE SYSTEM INSTALLATION (THEREFORE NO OBJECTION TO CONSTRUCTION OF GARAGE AT PROPOSED LOCATION (SRV) 1/14/00 - HOLE C INDICATED SLIGHTLY BETTER CONDITIONS BUT SOILS MAY <sup>BE</sup> UNFIT FOR CONVENTIONAL SYSTEM, ADVISED MR. SANDBERG OF LIMITED PROSPECTS FOR FUTURE ON-SITE REPAIR (SRV/CW)


DATE SYSTEM APPROVED 7/17/00 INSPECTOR Steven R. Krieg / CW (SRV)

evaluated by

NOTES:

- 1) B.R.L. information, if shown, was obtained from existing record plat or local agencies and is not guaranteed by NTT, Inc.
- 2) Building line and/or Flood Zone information is subject to the interpretation of the originator.
- 3) NTT, Inc. does not certify to unshown or unrecorded encroachments or overlaps.
- 4) Property markers not found, or guaranteed by this location.
- 5) Setback distance accuracy: 1".

\* Notes made by SRK/CW 1/14/00



Subject property is shown in Zone C on the National Flood Insurance Program Flood Insurance Rate Map of Howard County, Maryland, Panel # 30 of 45 Community Panel # 240044-0030 B Effective date: December 4, 1986

This is to certify that I have surveyed the property shown hereon, being known as  
**6279 Rockburn Hill West**  
 recorded in the Land Records of Howard County, Maryland in Plat Bk. Liber 1891 Folio 299 for the purpose of locating the improvements thereon.

This plat is of benefit to the consumer only insofar as it is required by a lender or a title insurance company or its agent in connection with contemplated transfer, financing, or refinancing purposes. This plat is not to be relied upon for the establishment of location of fences, garages, buildings, or other existing or future structures. This plat does not provide for the accurate identification of property boundary lines, but such identification may not be required for the transfer of title or for securing financing or refinancing.



LOCATION DRAWING  
 6279 Rockburn Hill West  
 1st election district  
 HOWARD COUNTY, MARYLAND

Scale:	1" = 50'
Date:	December 22, 1998
Field by:	JLM
Drawn by:	JLM
Drawing #	208BCEC

NTT Associates, Inc.  
 16205 Old Frederick Road  
 Mt. Airy, Maryland 21771  
 Ph. (410)442-2031  
 Fax No. (410)442-1315

Dun-Rite Septic Tank Service  
10439 Frederick Rd  
Ellicott city, md 21042  
(410) 461-3255

Dec 16, 1998  
Howard License  
H0-13-920

Mr. Jerry & Betty Reddell  
6279 West Rockburn Hill  
Baltimore, Md 21227  
410-796-8372

We Came On Dec 16, 1998, We located the Septic System .We Dug down to the lid, We Pumped the Septic Tank And then we Installed a Clean-out for future easy Septic Tank Cleaning for the New Owner and We also Certified the Septic Tank And The Septic System for Mr. & Mrs Jerry Reddell The Septic System are in Working Order at this time on this December 16, 1998.

Thank You,  
Dun-Rite Septic Tank Service  
C/o Curtis & Verna Jenkins

*Curtis & Verna Jenkins*

1/10/00

- Kept in File for Informative purposes only -  
\*however, has no bearing for Garage addition proposal. Also this septic was "certified" prior to July 1999. ~~After July 1999~~ ~~contractors/realtors~~ <sup>must</sup> take the approved course before being qualified to "certify" a septic system. Even ~~if~~ if the system was "certified" ~~prior~~ after July 1999 this certification doesn't tell us much. -SRK  
& we don't honor it.

**INSPECTION - SEPTIC SYSTEM CERTIFICATION**

Addendum No: **14**

Date of Offer: **NOVEMBER 24, 1998**

Addendum Date:

Property: **6279 ROCKBURN HILL WEST**

**SEPTIC SYSTEM CERTIFICATION**

This Contract is contingent upon Purchaser receiving a satisfactory Septic Certification by a licensed plumber, lender approved testing company or the appropriate County or State Health Department. Said test shall be performed not later than fifteen (15) days prior to settlement. Purchaser agrees to arrange for and complete the Septic System Certification at Purchaser's sole expense. Seller agrees to pay the cost of treatment and/or repair or replacement, if required, in an amount not to exceed two percent (2%) of the Contract purchase price.


Notwithstanding any provision herein, in no event shall Seller be obligated to pay more than two percent (2%) of the purchase price which may be required to certify septic system.

However, if Purchaser at Purchaser's option and expense agrees to pay for repairs and/or treatment exceeding the aforesaid two percent (2%) maximum, this Contract shall remain in full force and effect.

If this Contract shall become null and void as a result of this Septic Certification Contingency, upon execution of Releases, all deposit monies paid hereunder shall be returned to the Purchaser without further obligation or liability on the part of either party.

**TIME IS OF THE ESSENCE WITH REGARD TO THIS SEPTIC SYSTEM CERTIFICATION CONTINGENCY**

WITNESS



WITNESS

WITNESS

WITNESS

BUYER

BUYER

SELLER

SELLER

*[Signature]*  
11/25/98

Date

*[Signature]*  
11/24/98

Date

Date

Date

1/7/00 - Meeting

w/ Mr. Sandberg discussed proposal. Garage Addition  
He will consider our issues and reconsider his proposal. - SRK/CW  
Aware of septic issues



**HOWARD COUNTY HEALTH DEPARTMENT**

Diane L. Matuszak, M.D., M.P.H., County Health Officer

January 5, 2000

Brian Sandberg  
6279 Rockburn Hill Road  
Elkridge, MD 21075

RE: Building Permit Application  
Number: BOO121661  
6279 Rockburn Hill Road

Dear Mr. Sandberg:

This is to follow up on our recent conversation regarding the status of the above referenced building permit for a detached garage.

This office can not recommend approval of the above mentioned building permit application at this time, because of concerns regarding the condition of your existing septic system and whether or not adequate septic repair area exists for the installation of a future septic system.

The regulatory standard applicable to this situation is: Section 26.04.02.02 D (4) of the Code of Maryland Regulations which states a county may not issue a building permit "...until the Approving Authority has: Certified the existing on-site sewage disposal ... systems as capable of handling the existing sewage flows..." To meet this standard, we need confirmation that the facility is served by an adequate septic system with demonstrated area for one complete replacement system.

Unfortunately, this office has no records which can indicate the condition of your existing septic system and preliminary field investigations indicate that some of the potential repair area may be located in the same location as where you plan to have your proposed garage.


To continue the evaluation of this permit, we would need to conduct a repair percolation test (\$25 permit fee) in order to evaluate where appropriate soil conditions exist and to establish enough area for future septic system repair. This would involve excavation by a contractor with a backhoe at selected spots.

If you would like to proceed with review of this permit, it would be best to call this office at (410) 313-2640 in order to schedule a meeting where we can further discuss these issues. Thank you in advance for your cooperation in this matter.


Very truly yours,  
*Steven R. Krieg*  
Steven R. Krieg, Sanitarian  
Water and Sewerage Program

SRK  
cc: File

31



BALTIMORE C  
MAP 108



Building Address 6279 ROCKBURN HILL WEST  
Elkridge MD 21075 Rd

Suite/Apt. #: \_\_\_\_\_ SDP/WP/Petition #: \_\_\_\_\_

Census Tract 601161 Subdivision N/A

Section N/A Area N/A Lot N/A

Tax Map 32 Parcel 45 Grid 20

Zoning R-ET Map Coordinates 17H4 Lot size 1.09 Acre

Property Owner's Name BRIAN SANDBERG

Address 6279 ROCKBURN HILL WEST Rd

City ELKRIDGE State MD Zip Code 21075

Home Phone \_\_\_\_\_ Work Phone 410 379-8014

Applicant's Name & Mailing Address, (if other than stated hereon): \_\_\_\_\_

Phone \_\_\_\_\_ Fax 410-379-8056

Existing Use SFD

Proposed Use GARAGE (Detached)

Estimated Construction Cost \$ 9500.00

Description of Work DETACHED, FRAME,  
GARAGE - INTERIOR UNFINISHED

Contractor Company OWNER

Contact Person \_\_\_\_\_

Address \_\_\_\_\_

City \_\_\_\_\_ State \_\_\_\_\_ Zip Code \_\_\_\_\_

License No. \_\_\_\_\_

Phone \_\_\_\_\_ Fax \_\_\_\_\_

Occupant or Tenant OWNER

Contact Name \_\_\_\_\_

Address \_\_\_\_\_

City \_\_\_\_\_ State \_\_\_\_\_ Zip Code \_\_\_\_\_

Phone \_\_\_\_\_ Fax \_\_\_\_\_

Engineer or Architect Company \_\_\_\_\_

Contact Person \_\_\_\_\_

Address \_\_\_\_\_

City \_\_\_\_\_ State \_\_\_\_\_ Zip Code \_\_\_\_\_

Phone \_\_\_\_\_ Fax \_\_\_\_\_

**BUILDING DESCRIPTION - COMMERCIAL** **BUILDING DESCRIPTION - RESIDENTIAL**

**Building Characteristics**

Height: 22'

No. of stories: 1 1/2 + LOFT

Gross area, sq. ft. per floor: 1120 sq ft

Use group: \_\_\_\_\_

Construction type:  
 Reinforced Concrete  
 Structural Steel  
 Masonry  
 Wood Frame  
 State Certified Modular

**Utilities**

Water Supply:  
 Public  
 Private

Sewage Disposal:  
 Public  
 Private

Electric Yes  No   
 Gas Yes  No

Heating System:  
 Electric  Oil   
 Natural Gas   
 Propane Gas

Sprinkler system: N/A   
 Full  
 Partial  
 Other Suppression  
 # of Heads \_\_\_\_\_

**Building Characteristics**

SF Dwelling  SF Townhouse

Depth \_\_\_\_\_ Width \_\_\_\_\_

1st floor: \_\_\_\_\_

2nd floor: \_\_\_\_\_

Basement: \_\_\_\_\_

Finished Basement  Unfinished Basement   
 Crawl space  Slab on Grade

No. of Bedrooms \_\_\_\_\_

Multi-family dwellings:  
 No. of efficiency units: \_\_\_\_\_  
 No. of 1 BR units: 15  
 No. of 2 BR units: \_\_\_\_\_  
 No. of 3 BR units: \_\_\_\_\_

Other Structure: GARAGE  
 Dimensions: 30x40  
 Footings: CONCRETE  
 Roof: SHINGLE

State Certified Modular  
 Manufactured Home

**Utilities**

Water Supply:  
 Public  
 Private

Sewage Disposal:  
 Public  
 Private

Electric Yes  No   
 Gas Yes  No

Heating System:  
 Electric  Oil   
 Natural Gas   
 Propane Gas

Sprinkler system: N/A   
 NFPA #13D  
 NFPA #13R  
 Other \_\_\_\_\_

THE UNDERSIGNED HEREBY CERTIFIES AND AGREES AS FOLLOWS: (1) THAT HE/SHE IS AUTHORIZED TO MAKE THIS APPLICATION; (2) THAT THE INFORMATION IS CORRECT; (3) THAT HE/SHE WILL COMPLY WITH ALL REGULATIONS OF HOWARD COUNTY WHICH ARE APPLICABLE THERETO; (4) THAT HE/SHE WILL PERFORM NO WORK ON THE ABOVE REFERENCED PROPERTY NOT SPECIFICALLY DESCRIBED IN THIS APPLICATION; (5) THAT HE/SHE GRANTS COUNTY OFFICIALS THE RIGHT TO ENTER ONTO THIS PROPERTY FOR THE PURPOSE OF INSPECTING THE WORK PERMITTED AND POSTING NOTICES.

Applicant's Signature [Signature]  
 Title/Company OWNER

Print Name BRIAN SANDBERG  
 Date 12/8/99

Checks payable to: **DIRECTOR OF FINANCE OF HOWARD COUNTY**  
**\*\* PLEASE WRITE NEATLY AND LEGIBLY \*\***  
**- FOR OFFICE USE ONLY -**

AGENCY	DATE	SIGNATURE APPROVAL
<input checked="" type="checkbox"/> Land Development, DPZ		
<input checked="" type="checkbox"/> State Highways		
<input checked="" type="checkbox"/> Building Official		
<input checked="" type="checkbox"/> Dev. Engineering, DPZ	<u>1/14/00</u>	<u>Steven R. Kueg</u>
<input checked="" type="checkbox"/> Health		
<input checked="" type="checkbox"/> Fire Protection		

Is Sediment Control approval required prior to issuance?  
 YES  NO

CONTINGENCY CONSTRUCTION START:   
 ONE STOP SHOP:

**DPZ SETBACK INFORMATION**

Front: 5' Min  
 Rear: 30' Min  
 Side: 10' Min  
 Side St.: \_\_\_\_\_

All minimum setbacks met?  
 YES  NO

Is Entrance Permit required?  
 YES  NO

Historic District?  
 YES  NO

Lot Coverage for New Town Zone \_\_\_\_\_  
 SDP/Red-line approval date \_\_\_\_\_

**PROPERTY ID#:** 44300


Filing fee \$ 25.00  
 Permit fee \$ \_\_\_\_\_  
 Excise tax \$ \_\_\_\_\_  
 Sub-total paid \$ \_\_\_\_\_  
 Add'l permit fee \$ \_\_\_\_\_  
 TOTAL FEES \$ \_\_\_\_\_  
 Balance due \$ \_\_\_\_\_  
 Check # Cash  
 Validation # 25957

Accepted by [Signature]

B00140251

2/6/03-  
Discussion w/ Mr.  
Sandberg. Ex. well  
to be sealed prior  
to construction of  
house expansion  
- SRK

- NOTES:
- 1) B.R.L. information, if shown, was obtained from existing record plat or local agencies and is not guaranteed by NTT, Inc.
  - 2) Building line and/or Flood Zone information is subject to the interpretation of the originator.
  - 3) NTT, Inc. does not certify to unshown or unrecorded encroachments or overlaps.
  - 4) Property boundaries not shown or guaranteed by this location.
  - 5) Setback distances accurate: 1/4"



Subject property is shown in Zone C on the National Flood Insurance Program Flood Insurance Rate Map of Howard County, Maryland, Panel # 30 of 45 Community Panel # 240044-0030 B Effective date: December 4, 1986

This is to certify that I have surveyed the property shown hereon, being known as  
**6279 Rockburn Hill West**  
 recorded in the Land Records of Howard County, Maryland in Plat Bk. Liber 1891 Folio 299 for the purpose of locating the improvements thereon.




LOCATION DRAWING  
 6279 Rockburn Hill West

1st election district  
 HOWARD COUNTY, MARYLAND

NTT Associates, Inc.  
 16205 Old Frederick Road  
 Mt. Airy, Maryland 21771  
 Ph. (410)442-2031  
 Fax No. (410)442-1315

Scale:	1" = 50'
Date:	December 22, 1998
Field by:	JLM
Drawn by:	JLM
Drawing #	208BCEC

This plat is of benefit to the consumer only insofar as it is required by a lender or a title insurance company or its agent in connection with contemplated transfer, financing, or refinancing purposes.  
 This plat is not to be relied upon for the establishment of location of fences, garages, buildings, or other existing or future structures.  
 This plat does not provide for the accurate identification of property boundary lines, but such identification may not be required for the transfer of title or for securing financing or refinancing.



\*\*\*\*\*  
WATER WELL ABANDONMENT SEALING REPORT FORM  
\*\*\*\*\*

SUBMIT COPIES OF COMPLETED FORM TO:

- \* COUNTY ENVIRONMENT AGENCY (contact MDE, WMA if address needed)
- \* WELL OWNER
- \* MDE, WATER MANAGEMENT ADMINISTRATION, WELL PROGRAM

DATE WELL ABANDONED: 3/20/03 (month/day/year)

\* PERMIT NUMBER OF ABANDONED WELL (if any) \_\_\_\_\_

-NA-

\* PERMIT NUMBER OF REPLACEMENT WELL \_\_\_\_\_

No Tag


\* PERSON ABANDONING WELL: Brian Sandberg

WELL DRILLERS LICENSE NUMBER: NA

\* OWNER'S NAME: Brian Sandberg

CIRCLE: MWD/MSD/MGD

\* WELL LOCATION:  
COUNTY: Howard  
NEAREST TOWN: Elkridge  
TAX MAP 32 BLOCK 20 PARCEL 45  
SUBDIVISION: NA  
SECTION: \_\_\_\_\_ LOT: \_\_\_\_\_  
NEAREST ROAD: 6279 Rockburn Hill Rd



SHOW WELL LOCATION BY X WITHIN BOX

MARYLAND GRID COORDINATES

BOX NUMBER  
E 877  
N 506

\* TYPE OF WELL BEING ABANDONED:

- DRILLED
- BORED/AUGURED
- OTHER (specify) \_\_\_\_\_
- JETTED
- HAND DUG

\* USE CODE:

- DOMESTIC
- IRRIGATION
- TEST/OBSERVATION
- MUNICIPAL/PUBLIC
- INDUSTRIAL

\* TYPE OF CASING:

- STEEL
- CONCRETE
- PLASTIC
- OTHER (specify) \_\_\_\_\_

\* SIZE OF CASING: 3+ feet INCHES IN DIAMETER

\* DEPTH OF WELL: 15 FEET DEEP

\* WAS ANY CASING REMOVED? YES  NO   
if yes, length removed, in feet: \_\_\_\_\_

\* WAS CASING RIPPED OR PERFORATED? YES  NO

LOG OF SEALING MATERIAL

MATERIAL	FEET	
	FROM	TO
Topsoil	0'	5.5'
Concrete	5.5'	8'
# 2 stone	8'	15'

SIGNATURE-MASTER WELL DRILLER OR SUPERVISING SANITARIAN  
Steven Roger Krieg

LICENSE # 1231

CIRCLE ONE MWD/MSD/MGD

DATE 3/20/03

WATER WELL ABANDONMENT-SEALING REPORT FORM

SUBMIT COPIES OF COMPLETED FORM TO:

- \* COUNTY ENVIRONMENT AGENCY (contact MDE, WMA if address needed)
- \* WELL OWNER
- \* MDE, WATER MANAGEMENT ADMINISTRATION, WELL PROGRAM

DATE WELL ABANDONED: 3/20/03 (month/day/year)

\* PERMIT NUMBER OF ABANDONED WELL (if any) \_\_\_\_\_

- NA -

\* PERMIT NUMBER OF REPLACEMENT WELL \_\_\_\_\_

No Tag


\* PERSON ABANDONING WELL: Brian Sandberg

WELL DRILLERS LICENSE NUMBER: NA

\* OWNER'S NAME: Brian Sandberg

CIRCLE: MWD/MSD/MGD

\* WELL LOCATION:  
 COUNTY: Howard  
 NEAREST TOWN: Elkridge  
 TAX MAP 32 BLOCK 20 PARCEL 45  
 SUBDIVISION: NA  
 SECTION: \_\_\_\_\_ LOT: \_\_\_\_\_  
 NEAREST ROAD: 6279 Rockburn Hill Rd



SHOW WELL LOCATION  
 BY X WITHIN BOX

MARYLAND GRID COORDINATES

BOX NUMBER  
 E 877  
 N 506

\* TYPE OF WELL BEING ABANDONED:

- DRILLED
- BORED/AUGURED
- OTHER (specify) \_\_\_\_\_
- JETTED
- HAND DUG

\* USE CODE:

- DOMESTIC
- IRRIGATION
- TEST/OBSERVATION
- MUNICIPAL/PUBLIC
- INDUSTRIAL

\* TYPE OF CASING:

- STEEL
- CONCRETE
- PLASTIC
- OTHER (specify) \_\_\_\_\_

\* SIZE OF CASING: 3 1/2 feet INCHES IN DIAMETER

\* DEPTH OF WELL: 15 FEET DEEP

\* WAS ANY CASING REMOVED? YES  NO   
 if yes, length removed, in feet: \_\_\_\_\_

\* WAS CASING RIPPED OR PERFORATED? YES  NO

LOG OF SEALING MATERIAL

MATERIAL	FEET	
	FROM	TO
Topsoil	0	5.5'
Concrete	5.5'	8'
# 2 stone	8'	15'


SIGNATURE - MASTER WELL DRILLER OR SUPERVISING SANITARIAN: Steven Roger Krieg

LICENSE #: 1231

CIRCLE ONE: MWD/MSD/MGD

DATE: 3/20/03

6279 Rockburn Mill



Concrete 4+ Yrds  
5'6" from Concrete → Rim

6279 Rockham Hill



Stone Slingers  
4 Ton Stone

6279 Reklam Hill 22



Stone Filled to  
8' From Rim

6279 Rockburn Hill Rd



Laarge Concrete  
4.7 Yards → 5.5 Ft  
From Rim