

State Office Building  
ANNAPOLIS, MARYLAND 21401

DEPARTMENT OF  
WATER RESOURCES

APPLICATION MUST BE SUBMITTED AND PERMIT RECEIVED BEFORE DRILLING IS STARTED.

APPLICATION FOR PERMIT TO DRILL WELL

70.267

Owner Gordon Walker  
Street or R. F. D. \_\_\_\_\_  
Post Office Laurel Md

Driller Doug Brown License Number 56  
Street or R. F. D. \_\_\_\_\_  
Post Office Mt Airy Md  
Date May 13 1965

Quantity of Water to be Produced 3 G.P.M.  
Total Quantity Needed For Use 1000 G.P.D.  
Use for Water House  
Approximate Depth of Well (feet) 80 ft  
Method of Drilling to be used Cable

Location of Well  
Subdivision Branchburg  
Section 1 Lot 23  
County Howard  
Nearest Town Laurel  
Distance from Town 1 mile  
Direction from Town north east

Is this a Replacement Well? Yes - No  
If YES, indicate date abandoned well is to be sealed: \_\_\_\_\_  
and by whom: \_\_\_\_\_

Description of Location of Well  
(This information should be definite enough to permit locating well on a county map).  
Near what road Branchburg Road  
On which side of road north  
(North, East, South, West)

PERMIT TO DRILL WELL  
(Not To Be Filled In By Driller)


Well Permit No. H-65-11-436

Samples of Cuttings Required by Department:  Yes  No  
Owner Requires Permit to Appropriate Water:  Yes  No  
Owner Has Permit to Appropriate Water:  Yes  No

Appropriation Permit No. \_\_\_\_\_  
The applicant is herewith granted a permit to drill this well subject to the conditions stipulated.  
Daub W. McKee Director 5/17/65 Date

**THIS PERMIT IS NOT TRANSFERABLE**  
WITHOUT WRITTEN PERMISSION FROM THE DEPARTMENT  
Special conditions that must be observed:

Distance from road 100 ft  
Draw a sketch below showing location of well in relation to nearby towns, roads and streams with north in the direction of the arrow, and give distance from well to nearest road junction or stream crossing shown on the sketch.



Health Department Approval of Application  
\_\_\_\_\_  
County Department of Health  
or  State Department of Health  
Approved by \_\_\_\_\_  
Title \_\_\_\_\_  
Date \_\_\_\_\_

STATE OF MARYLAND  
 DEPARTMENT OF HEALTH AND MENTAL HYGIENE  
 Laboratories and Research Administration  
 16 E. 23rd Street, Baltimore, Maryland 21218

BACTERIOLOGICAL WATER REPORT 790

Date & Hour: Rec'd APR 30 1973 3<sup>20</sup> Exam. APR 30 1973  
 Rept. MAY 2 1973 Bacteriologist J. L. ...

PRESUMPTIVE TEST

ml. of Sample	10	10	10	10	10	1	.1
Gas, 24 hours	—	—	—	—	—		
Gas, 48 hours	—	—	—	—	—		

Legend

\*using Lauryl Sulfate Trypticase broth at 35° C. incubation  
 †using Brilliant Green Lactose Bile broth at 35° C. incubation  
 ‡using EC broth at 44.5° C. incubation

Bottle No. BS 4 Town Central Laboratory  
 Source of Sample 10826 Brookman Rd., Bryans County Howard  
 Public  Private  Treated  Untreated   
 pH — Res. Cl: Free — Total — Iced: Yes  No   
 Collected: Date 4/30/73 Hour 11:40 Collector C. Stecker  
 Remarks —  
 Lab. No. 19006 Thiosulfate: Pres.  Absent  Undetermined

CONFIRMED TEST

ml. of Sample	10	10	10	10	10	1	.1
Coliforms	†	—	—	—	—		
Fecal Coliforms	‡						

Coliforms / 100 ml. (Membrane Filter) =

Recall  
7/10/73  
2:30 P.M.  
at site

June 29, 1973

Mr. Marle Kessler *725-7200*  
Silver Key Realtors  
405 Main Street  
Laurel, Maryland

*10825*  
RE: 10825 Braeburn Road  
Clarksville, Maryland

Dear Sir:

Section 12.104 of the Howard County Code states: "The Board of Health, the County Health Officer, Sanitarian or his representative, shall take cognizance of all conditions dangerous to health and may on their own initiative institute an investigation."

On Thursday, June 14, 1973, the investigation revealed an overflowing private sewage disposal system on property owned by you and located at 10825 Braeburn Road, Clarksville, Maryland.

In my capacity, as a Sanitarian, with the Howard County Health Department, I have determined that this overflowing sewage is of such a condition that it creates a public nuisance which endangers the public health.

To abate this unhealthy nuisance you must:

1. Obtain a permit to repair the system.
2. Open up the ground and have the Sanitarian recommend the repair system, and,
3. have the system inspected by the Health Department.

You must comply with the provisions of this notice within thirty (30) days from the date of this notice, or apply to the Executive Secretary of the Board of Health for a hearing within ten (10) days from the date of this notice. If you do not apply for a hearing within the prescribed time and, if, you do not comply with this directive a summons will be issued directing you to appear before the District Court of Howard County for a trial.

A copy of the Howard County Code is available for you to see at the Health Department.

Very truly yours,

Charles B. Streaker,  
Sanitarian

Send "Bill" 33  $\leftrightarrow$  6/14/73  $\leftarrow$  (Recall 7/12/73) check for steps water

FILE Water Sample DATE REPORTED 4/23/73  
PROPERTY OWNER C. Brent Bargaron  
P.O. ADDRESS 10826 Braeburn Rd. off Cedar Lane TELEPHONE 531-5848  
DIRECTIONS TO PROPERTY Clarksville, Md. Rt 108  
"Braeburn"

INFORMANT  
Bacteria # BS 4 Keesler 192-0339  
725-7200  
"Bill 33" ? Mrs. MERLE KEESLER  
Silver Key Realtor; 405 Main Street  
Lanard Md

see back

CONDITION FOUND Renter has contacted him about  
Keesler out with contractor Mrs  
Bargaron stated 3 weeks up on 4/28/73  
4/30/73 sample taken at 11:40 kitchen sink  
No treatment C.B.S. & W.Z.  
5/10/73 send H1, '81 letter. "Hold I would  
like this sheet <sup>back</sup> please!! C.B.S.

ACTION TAKEN  
5/10/73 - Letter sent this date bacteria  
5/11/73 5/14/73 AM Mr. Keesler had man out  
on Saturday 5/12/73 to repair system accordi  
to Mr. Bargaron per phone conversation in main  
Called Silver Key Realtors - Mr. Keesler to C.B.S.  
call back. C.B.S. Keesler called back discussed  
with Mr. Wine. Mr. Wine stated to check area

FINAL DISPOSITION & report back. 5/14/73 Area checked & discuss  
with Mrs. Bargaron - area dry & no evidence  
of overflow or water laying in pools. Area recentl  
excavated to form slight swale to drain water  
from back of house. Hold & recheck in July '1973.

On 6/14/73 area checked + sewage noted after  
a dry spell of 6-8 days!! Send Bill "33" to  
Silver Key concerning 10826 Bradburn Rd

Check: - 6/14/73

also R. Nieman  
Conn.

7/5/73 Mr. Kessler called. Discussed situation  
+ set up appointment for site.

7/10/73 At site ~~to suggest~~ <sup>suggest</sup> a trench 50' long  
depth depends on soil. location off of  
septic tank to right <sup>side</sup> of lot.

Ms. Baragon stated to inspector they had  
been a war for a month. On 7/10/73 no  
overflow. No one showed at site from 2:15-  
to 3:45. Mr. Kessler came, discussed trench  
to have in by end of August '73.

To secure permit within next 2 week  
+ set up visual hole appointment.

C.B.S.