

02/05/2004 15:02

Call

Seq Date
C1 09071973 HD-73-0260

WELL COMPLETION REPORT

COMPLETION

Completion Date: 08151973

Depth of Well: 250

Number Unsuccessful:

Hydractured?:

CASING

Casing Type: ST

Casing Diameter: 6

Casing Depth: 40

Casing Height: +02

PUMPING TEST

Hours Pumped: 6

Pumping Rate: 6

Water Level Before: 40

Water Level During: 80

Type Pump Used: A

GROUTING

Grouted?: Y

Grout Type: CM

Grout From: 0

Grout To: 40

SCREENS

Type	Top	Bottom
1	HD 40	250
2	<input type="text"/>	<input type="text"/>
3	<input type="text"/>	<input type="text"/>

Screen Diameter:

PUMP INSTALLED

Pump Installed?: NO

Type of Pump Installed:

Capacity:

Pump Horsepower:

Pump Column Length:


Flowing Telescoping Log Indicator Closed Abandoned

Abandon Date:

Well Log

Mica Soil 0-40 ft

Mica Rock 40-250 ft ✓ hit water



WIN 7750 IN 2013



Call

04161973 HO730260 HO-73-0260

KRAMER, LEE H

862 QUINCE ORCHARD RD

GAITHERSBURG MD 20760

DILLON, HOWARD J MWD0209

5 300

D

150 AIR-PER

N

HO HOWARD COUNTY

TEN OAK HILLS 2 4

DAYTON 1 MI S

MORINGSTAR DR S 100 FT

04121973

510000 800000

173964 400026

39.233831 76.9997 0