

CASELL TESTING, INC.

ENVIRONMENTAL SAMPLING AND TESTING
10940 BEAVER DAM ROAD, HUNT VALLEY, MD 21030-2211
(410) 252-7742

REPORT DATE: May 6, 2005

County Howard

Lab Number 05-2144

Sample iced Yes

Residual Cl₂ <0.1 mg/L Yes

cc: County Health Dept. Yes

CERTIFICATE OF ANALYSIS

Maryland State Certified Water Quality
Laboratory No. 115

REQUESTER: Mr. Dave Randlett
2919 Duvall Road
Woodbine, Maryland 21797

Property Sampled: U&O: 2919 Duvall Road

Station Sampled: Basement laundry tub tap

Tax Map #: 13

Date/Time Sampled: May 5, 2005 11:10 am

Parcel #: 96

Owner, Telephone No.: Randlett

Sampler: 6724GP

Subdivision Name: 1200' N of WRFLD

Lot Number: 21

Building Permit No.: B00146519

Well Number: Tag not visible

Observation: 1-Piece Cap
Cap tight
Jet pump in basement

RESULTS OF ANALYSIS:

PARAMETER	RESULT	METHOD	*MCL/**SMCL	
Nitrate	7.3 mg/L as N	SM 4500D	*10 mg/L as N	Pass
Turbidity	<1.0 NTU	EPA 180.1	*10 NTU	Pass
pH	5.4 Units	EPA 150.1	**6.5-8.5 Units	***
Sand	Negative		Negative	
Total Coliform	Absent	SM 9223B	*Absent	SAFE
E. coli	Absent	SM 9223B	*Absent	SAFE

Treatment/Conditioning: None

***A non-enforceable parameter that may cause cosmetic effects or aesthetic effects (such as taste, odor, or color) in drinking water.

Heather R. Beam

Heather R. Beam

*MCL = Maximum Contamination Level

**SMCL = Secondary Maximum Contamination Level