





INDICATE NORTH. - NAME ADJOINING ROADWAY AS BASE LINE.

PERMIT CARD none seen

SEPTIC TANK, LEVEL 1250 gal - CLEANOUTS ST / DW

DISTRIBUTION BOX, LEVEL \_\_\_\_\_

TILE FIELD, DEPTH \_\_\_\_\_ FT. TRENCH WIDTH \_\_\_\_\_ FT.

GRAVEL DEPTH \_\_\_\_\_ IN. TOTAL LENGTH \_\_\_\_\_ FT.

NUMBER OF TRENCHES \_\_\_\_\_ TOTAL BOTTOM AREA \_\_\_\_\_

SEEPAGE PITS, INSIDE DIAMETER outside perimeter 15x15x18x15 FT. DEPTH BELOW INLET 7 1/2 FT.

ABSORBENT AREA ~520 SQ. FT.

REMARKS 8/20/76 Sewer leaves house ~ 6' below grade

DW is 12' below orig grade

met Pat Lendrum @ site; DW appears to be w/in

10-15' of specified location; Recommend that

Lendrum be advised that 18' diam. DW is to be

DATE SYSTEM APPROVED 8/20/76 INSPECTOR William H. Zapp