

Tax ID - 05-3571959/28/93
48 10:30-11:00

PERMIT (2:30 Back)

SEWAGE DISPOSAL SYSTEM

MARYLAND STATE DEPARTMENT OF HEALTH DISTRICT _____

P 45274

A REPAIR

DATE 11/27/89

DATE SYSTEM APPROVED 9/28/93

INSPECTOR C. Bell

9/28
10:30
11:00
admits
11/20
9/28/93
P.M.V.

HOWARD COUNTY
BUREAU OF ENVIRONMENTAL HEALTH
461-9933

INDEXED

Ray Namie IS PERMITTED TO INSTALL _____ ALTER X

ADDRESS _____ PHONE 934 854-9827

SUBDIVISION GREEN HILL MANOR ROAD 6718 Mink Hollow Road LOT 15-BLOCK A

PROPERTY OWNER _____ Ray Name David Vukmen Tranche

ADDRESS _____ Note 7/28 (already done)
IF GARBAGE GRINDER IS USED INCREASE SEPTIC TANK CAPACITY BY 50% AND ABSORPTION AREA BY 22%
GARBAGE GRINDER? YES _____ NO X
1/2" = 3' wide
last trench
1/2" = 2' wide

SEPTIC TANK CAPACITY 1250 GALLONS NUMBER OF BEDROOMS 4 125

REPAIR - CALL FOR INSPECTION WHEN GROUND IS OPENED SO SANITARIAN CAN RECOMMEND REPAIR.

9/28 2' wide trenches recommended admits for 2 & 3
trench C.B. (No permit card seen)
Note given per owner 9/28 (C.B.)

PLANS APPROVED BY C.B. for C. Williams admits 9/28/93 DATE 11/27/89

COVER NO WORK UNTIL INSPECTED AND APPROVED

NEITHER THE HOWARD COUNTY COUNCIL NOR THE HEALTH DEPARTMENT IS RESPONSIBLE FOR THE SUCCESSFUL OPERATION OF ANY SYSTEM

- NOTE: CLEANOUT REQUIRED EVERY 70 FEET OF SEWER LINE AND/OR AT 90° SWEEPS IN LINES FROM HOUSE TO DRAIN FIELDS
- NOTE: ALL PARTS OF SEPTIC SYSTEMS (I.E. TANK, DISTRIBUTION BOX, TRENCHES) TO BE 100 FEET FROM WELL (UNLESS OTHERWISE SPECIFICALLY AUTHORIZED)
- NOTE: IF DEEP TRENCHES ARE USED CALL FOR INSPECTION BEFORE AND AFTER PLACING GRAVEL IN TRENCHES
- NOTE: NO DRY WELL SHALL EXCEED 15 FOOT IN DIAMETER NO ABSORPTION TRENCH TO EXCEED 100 FEET IN LENGTH
- NOTE: ALL PIPE FROM HOUSE TO SEPTIC TANK MUST BE CAST IRON OR SCHEDULE 40 PVC OR ABS
- PERMIT VOID AFTER TWO YEARS
- NOTE: INSTALL STAND PIPE ON SEPTIC TANK AND DRY WELL. STAND PIPES MUST BE 6 INCHES IN DIAMETER. CAST IRON, CONCRETE OR TERRA COTTA OR PVC OR ABS ACCEPTED. IF TOP OF SEPTIC TANK IS DEEPER THAN 3 FEET, MANHOLE TO GRADE REQUIRED
- NOTE: DISTRIBUTION BOXES MUST HAVE BAFFLES

***INSTALLER IS RESPONSIBLE FOR OBTAINING FINAL APROVAL ON THIS PERMIT**

*CALL 461-9933 FOR INSPECTION OF SEPTIC SYSTEMS.

K 42017

- Check for
Well HO-67-W-68
 - Created 1966
 - Not seen on
As-Built 1993



