

Bureau of Environmental Health

8930 Stanford Blvd. Columbia, MD 21045
Main: 410-313-2640 | Fax: 410-313-2648
TDD 410-313-2323 | Toll Free 1-866-313-6300
www.hchealth.org
Facebook: www.facebook.com/hocohealth
Twitter: HowardCoHealthDep

Maura J. Rossman, M.D., Health Officer

March 28, 2016

Glenwood Baptist Church
C/O Mr. Thomas Cornwell
12196 Triadelphia Road
Ellicott City, MD 21042

Re: *Water Sample Results - PWSID # 1131073*

Dear Mr. Cornwell,

Sampling of the well water supply serving the Glenwood Baptist Church was conducted on March 23, 2016. Testing was performed as part of the Non-Community Water Supply (NCWS) monitoring program.

Results of this test indicate that the sample was free of E.coli and coliform bacteria. Sampling will continue on a quarterly basis to confirm a safe water supply.

A copy of the test result is enclosed for your information. If you have any further questions, you may contact me at kcook@howardcountymd.gov or 410-313-2774.

Sincerely,

Kathleen Cook, LEHS
Community Hygiene Program

Enclosure




Interactive Map

Map Layers Map Legend Search

All Layers

- Base Maps & Aerial Photos
- Annotation Layers
- HoCo Base Map Layers
 - Contours 2011
 - County Boundary
 - Stream Centerline Buffer 75ft
 - Building Permits (New)
 - Scanned PDF Drawings Intern
 - Address Points
 - Street Centerline
 - Metro Property
 - Property Boundaries
- Additional Layers
 - Sewer Infrastructure
 - Water Infrastructure
 - Study Areas
- Layer Overlays
 - Green Infrastructure - Hubs





Well cap



Pressure tank



Sediment Filter



UV light

TRANSIENT NONCOMMUNITY WATER SUPPLY SANITARY SURVEY

SYSTEM NAME Glenwood Baptist Church PWSID: 1131073

SITE ADDRESS & PLANT NAME: <u>3875 Rte 97</u> <u>Glenwood MD 21738</u>		ADC MAP / TAX MAP:
SITE CONTACT: <u>Tom Cornwell</u>		ESTIMATED DAILY POPULATION: TNC: <u>50/sunday</u> OTHER: <u>0</u>
SITE CONTACT PHONE: <u>410 977 5546</u>	SITE CONTACT EMAIL: <u>tomcor321@comcast.net</u>	# OF CONNECTIONS: <u>1</u>
PROPERTY OWNER: <u>Glenwood Baptist Ch % Carolyn Clemens</u>		NUMBER OF PLANTS: <input checked="" type="checkbox"/> SINGLE <input type="checkbox"/> MULTIPLE, #
OWNER PHONE:	OWNER EMAIL:	FACILITY TYPE & OPERATION
OWNER MAILING ADDRESS: <u>9240 Holsey Rd.</u> <u>Tamascus, MD 20872-2412</u>		<input type="checkbox"/> VISITOR CENTER <input type="checkbox"/> SUMMER CAMP <input type="checkbox"/> SERVICE STATION <input type="checkbox"/> RECREATION/ MARINA <input type="checkbox"/> REST AREA <input type="checkbox"/> MOTEL <input type="checkbox"/> FOOD SERVICE <input checked="" type="checkbox"/> CHURCH <input type="checkbox"/> OTHER:
OPERATOR: <u>Tom Cornwell</u>	CERTIFIED? <input checked="" type="checkbox"/> NO YES: G 1 2 3 4/SW 5/GWUDI	<input type="checkbox"/> SEASONAL OPERATION: (OR) open _____ close _____
OPERATOR PHONE: <u>410 977 5546</u>	OPERATOR EMAIL: <u>tomcor321@comcast.net</u>	<input checked="" type="checkbox"/> SYSTEM OPERATES YEAR ROUND

WATER QUALITY ISSUES		<input checked="" type="checkbox"/> PROTECTED <input type="checkbox"/> VULNERABLE
NITRATE MCL VIOLATION IN PAST 5 YEARS? <input checked="" type="checkbox"/> NO YES: ONGOING RESOLVED	GROUND WATER UNDER DIRECT INFLUENCE? YES <input checked="" type="checkbox"/> NO	
IF RESOLVED, HOW? <input type="checkbox"/> CONTAMINATION REMOVED <input type="checkbox"/> TREATMENT INSTALLED	TREATMENT INSTALLED? YES <input checked="" type="checkbox"/> NO	
<input type="checkbox"/> ALTERNATIVE NITRATE LEVEL (ANL) GRANTED POSTED? NO YES	E. COLI SOURCE POSITIVE (GWR)? YES <input checked="" type="checkbox"/> NO	
TOTAL COLIFORM VIOLATION IN PAST 5 YEARS? NO YES: ONCE MULTIPLE ONGOING		
E. COLI VIOLATION IN PAST 5 YEARS? NO YES: ONCE MULTIPLE ONGOING		

SITE SCHEMATIC: INDICATE WELL, PLANT, STORAGE AND APPROXIMATE DISTANCE TO STRUCTURES, ROADS, AND POTENTIAL SOURCES OF CONTAMINATION	WERE ANY SIGNIFICANT DEFICIENCIES FOUND ?
	SOURCE YES <input checked="" type="checkbox"/> NO TREATMENT YES <input checked="" type="checkbox"/> NO DISTRIBUTION YES <input checked="" type="checkbox"/> NO FINISHED STORAGE YES <input checked="" type="checkbox"/> NO PUMPS & CONTROLS YES <input checked="" type="checkbox"/> NO MONITORING & REPORTING YES NO MANAGEMENT & OPERATION YES NO OPERATOR COMPLIANCE YES NO CORRECTIVE ACTION DATE:
SEPTIC* SEWER LINE* PETROLEUM* FERTILIZER* ANIMALS* SURFACE WATER* GAS* OTHER	

WATER SYSTEM INSPECTION SUMMARY, COMMENTS, REQUIRED ACTIONS	REASON FOR INSPECTION: <input checked="" type="checkbox"/> ROUTINE <input type="checkbox"/> CORRECTIVE
<p><u>After issues with bacteria contamination, repairs were made to the well conduit, the well cap was replaced, sediment & UV treatment were added, and pressure tank replaced.</u></p>	
INSPECTION DATE: <u>September 23, 2015</u>	INSPECTED BY: <u>Terri Keeland</u>
SYSTEM REPRESENTATIVE: <u>Tom Cornwell</u>	

Glenwood Missionary Baptist Church

3875 Washington Rd or Rt 97

Glenwood Md.

Any Questions Contact




Work 988-9221

Tom Cornwell

Home 988-9313

12196 Triadelphia Rd
Ellicott City, Md 21042


Property Line



34'

Well site
OK as
staked
6/29/94
ALM

Rt 97



Grave Yard

Property Line