


December 14, 2015

Dear Mr. Kevin Wolf,

I would like to retain the well at my property 10710 Cleos Court Columbia, MD 21044 for irrigation purposes. I have hired a contractor by the name of Terry Conrad at Oak Hill Construction to complete the required disconnection. The well water was inspected in the last 3 months, and I will send you a copy of that document as soon as I am able to locate it. Thank you for your help!

Noreen Ramienski
10710 Cleos Court
Columbia, MD 21044

A handwritten signature in cursive script that reads "Noreen Ramienski". The signature is written in black ink and is positioned below the typed name and address.



P.O. Box 138
 Ashton, Md 20861
 301-854-1333 Main 301-854-1538 Fax
 NationalWaterService.com

DATE INVOICE #
 9/21/2015 40279

PAID
09/22/2015

BILL TO

Noreen Ramienski
 10710 Cleos Court
 Columbia, MD 21044

IF YOU ARE ON WELL WATER....

HAVE YOU TESTED FOR RADON IN THE
 WATER?

**YOUR #1 SOURCE FOR COMPLETE WATER
 TREATMENT AND WELL PUMP SERVICE**


P.O. NO. TERMS

Due on receipt

QTY	DESCRIPTION	RATE	AMOUNT
1	Service Call - First Hour	115.00	115.00
1	Incremental labor charge - \$25.00 for each 15 minute interval after 1st hour.	25.00	25.00
1	Shock Well (Pellet)	20.00	20.00

Serviced By - Dave


Total \$160.00



HOME LAND SEPTIC CONSULTING, LLC

p:443-995-5385 | info@mdwellandseptic.com | www.homelandseptic.com

Sampled for:	Potability	Property Address: 10710 Cleos Court Columbia, MD 21044	Sample Date:	8/27/2015
Additional Samples:			Sample Time:	8:15 AM
Impurity:		Result:	Pass/Fail Level	
Total Coliform Bacteria		FAIL (Present)	Present/Absent	
E.coli Bacteria		Pass (Absent)	Present/Absent	
Nitrates:		Pass 0.7 mg/l	(Over 10.0 mg/l is failing)	
Turbidity:		Pass 0.4 NTU	(Over 10.0 NTU is "high")	
pH:		6.91	(6.5-8.5 is generally accepted)	

Well Tag:		Water Conditioning:	Physical Well Condition:	
Well Tag #:	HO 73 2751	Currently, there appears to be a water softener, acid neutralizer, and sediment filter.	Well Casing:	24" Above Grade
GPM at Drilling:	6		Conduit:	None
Well Depth:	185 Feet		Well Cap:	Loose
Static Water Level at Drilling:	5 Feet		Representatives Signature:	
Well was drilled on:	5/10/1978			

The Health Departments recommends that you test the water every 3-5 years.